

Trail Access Information Summary – Main Trail

| | | | |
|---|--|---|-------------------|
| Park Name | South Cape May Meadows | | |
| Trail Name | Main Trail | | |
| Length | 0.4 mi (0.6 km) One Way 0.8 mi (1.2 km) Round Trip | | |
| Elevation Gain | 15.7 ft (4.79 m) | | |
| Elevation Loss | 18.8 ft (5.74 m) | | |
| Trail Uses Allowed | Walking, Jogging, Photography, Wildlife Viewing, Trained Services Dogs | | |
| Trail Uses NOT Allowed | Biking, Dog Walking, Plant Harvesting, Camping, Fishing, Drone Use | | |
| Typical Grade | 1.8% | Max = 12.8% (near dune crossings) | |
| | Standard Ramp Grade is 8.3% | | |
| Typical Cross Slope | 1.2% | Max = 10.7% | |
| Typical Tread Width | 63 in (159.9 cm) | Min = 36 in (91.4 cm) | |
| Surface Type | Crushed Stone (Fines) | | |
| Surface Category | 0.0 % of Trail is Paved 2.7 % of Trail is Hard 96.4 % of Trail is Firm | 0.9 % of trail is Soft 0.0 % of trail is Very Soft | |
| Obstructions: | | | |
| Type: | Size (Height): | Remaining Tread: | Location: |
| Water Bar | 5 in (12.7 cm) | 14 in (35.6 cm) | 62.6 ft (19.08 m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| Warning: Trail conditions may have changed since 2024-09-09 when this trail was assessed. Temporary obstacles were not mapped. | | | |
| Maximum grades and cross-slopes may vary. Obstructions less than <u>5 in (12.7 cm)</u> or outside of the tread area <u>36 in (91.4 cm)</u> wide by <u>72 in (182.9 cm)</u> high were not reported. Minimum clearance width boundaries were at least <u>???</u> in (<u>???</u> cm) high | | | |
| Data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP). | | | |

Trail Access Information Summary – Boardwalk Trail

| | | | |
|---|---|-----------------------------|------------------|
| Park Name | South Cape May Meadows | | |
| Trail Name | Boardwalk Trail | | |
| Length | 0.6 mi (1.0 km) One Way 1.2 mi (2.0 km) Round Trip | | |
| Elevation Gain | 30.8 ft (9.38 m) | | |
| Elevation Loss | 8.7 ft (2.67 m) | | |
| Trail Uses Allowed | Walking, Jogging, Photography, Wildlife Viewing, Trained Services Dog | | |
| Trail Uses NOT Allowed | Biking, Dog Walking, Plant Harvesting, Camping, Fishing, Drone Use | | |
| Typical Grade | 1.2% | Max = 3.2% | |
| | Standard Ramp Grade is 8.3% | | |
| Typical Cross Slope | 0.5% | Max = 2.9% | |
| Typical Tread Width | 60 in (152.4 cm) | Min = 60 in (152.4 cm) | |
| Surface Type | Recycled Plastic Boardwalk | | |
| Surface Category | 0.0 % of Trail is Paved | 0.0 % of trail is Soft | |
| | 83.3 % of Trail is Hard | 0.0 % of trail is Very Soft | |
| | 16.7 % of Trail is Firm | | |
| Obstructions: | | | |
| Type: | Size (Height): | Remaining Tread: | Location: |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| Warning: Trail conditions may have changed since 2024-09-18 when this trail was assessed. Temporary obstacles were not mapped. | | | |
| Maximum grades and cross-slopes may vary. Obstructions less than <u>5 in (12.7 cm)</u> or outside of the tread area <u>36 in (91.4 cm)</u> wide by <u>72 in (182.9 cm)</u> high were not reported. Minimum clearance width boundaries were at least <u>???</u> in (<u>???</u> cm) high | | | |
| Data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP). | | | |

Trail Access Information Summary – State Park Connection

| | | | |
|---|--|------------------------------|------------------|
| Park Name | South Cape May Meadows | | |
| Trail Name | State Park Connection Trail | | |
| Length | 0.2 mi (0.4 km) One Way 0.4 mi (0.8 km) Round Trip | | |
| Elevation Gain | 6.9 ft (2.11 m) | | |
| Elevation Loss | 8.1 ft (2.46 m) | | |
| Trail Uses Allowed | Walking, Jogging, Photography, Wildlife Viewing, Trained Services Dogs | | |
| Trail Uses NOT Allowed | Biking, Dog Walking, Plant Harvesting, Camping, Fishing, Drone Use | | |
| Typical Grade | 1.2% | Max = 5.7% | |
| | Standard Ramp Grade is 8.3% | | |
| Typical Cross Slope | 2.0% | Max = 7.5% | |
| Typical Tread Width | 76 in (192.8 cm) | Min = 72 in (182.9 cm) | |
| Surface Type | Sand | | |
| Surface Category | 0.0 % of Trail is Paved | 42.3 % of trail is Soft | |
| | 0.0 % of Trail is Hard | 57.7 % of trail is Very Soft | |
| | 0.0 % of Trail is Firm | | |
| Obstructions: | | | |
| Type: | Size (Height): | Remaining Tread: | Location: |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| Warning: Trail conditions may have changed since 2024-09-09 when this trail was assessed. Temporary obstacles were not mapped. | | | |
| Maximum grades and cross-slopes may vary. Obstructions less than <u>5 in (12.7 cm)</u> or outside of the tread area <u>36 in (91.4 cm)</u> wide by <u>72 in (182.9 cm)</u> high were not reported. Minimum clearance width boundaries were at least <u>???</u> in (<u>???</u> cm) high | | | |
| Data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP). | | | |

Trail Access Information Summary – Dune Connection Trail

| | | | |
|---|--|-----------------------------|------------------|
| Park Name | South Cape May Meadows | | |
| Trail Name | Dune Connection Trail | | |
| Length | 0.1 mi (0.2 km) One Way 0.2 mil (0.4 km) Round Trip | | |
| Elevation Gain | 2.9 ft (0.88 m) | | |
| Elevation Loss | 5.7 ft (1.75 m) | | |
| Trail Uses Allowed | Walking, Jogging, Photography, Wildlife Viewing, Trained Services Dogs | | |
| Trail Uses NOT Allowed | Biking, Dog Walking, Plant Harvesting, Camping, Fishing, Drone Use | | |
| Typical Grade | 1.3% | Max = 3.9% | |
| | Standard Ramp Grade is 8.3% | | |
| Typical Cross Slope | 1.6% | Max = 4.5% | |
| Typical Tread Width | 80 in (203.2 cm) | Min = 80 in (203.2 cm) | |
| Surface Type | Crushed Stone (Fines) | | |
| Surface Category | 0.0 % of Trail is Paved | 4.1 % of trail is Soft | |
| | 0.0 % of Trail is Hard | 0.0 % of trail is Very Soft | |
| | 95.9 % of Trail is Firm | | |
| Obstructions: | | | |
| Type: | Size (Height): | Remaining Tread: | Location: |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| Warning: Trail conditions may have changed since 2024-09-09 when this trail was assessed. Temporary obstacles were not mapped. | | | |
| Maximum grades and cross-slopes may vary. Obstructions less than <u>5 in (12.7 cm)</u> or outside of the tread area <u>36 in (91.4 cm)</u> wide by <u>72 in (182.9 cm)</u> high were not reported. Minimum clearance width boundaries were at least <u>???</u> in (<u>???</u> cm) high | | | |
| Data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP). | | | |

Trail Access Information Summary- East Trail Spur

| | | | |
|---|--|------------------------------|------------------|
| Park Name | South Cape May Meadows | | |
| Trail Name | East Trail Spur | | |
| Type | Spur – Out and Back | | |
| Length | 0.3 mi (0.4 km) One Way 0.6 mi (0.8 km) Round Trip | | |
| Elevation Gain | 0.9 ft (0.28 m) | | |
| Elevation Loss | 34.8 ft (10.60 m) | | |
| Trail Uses Allowed | Walking, Jogging, Photography, Wildlife Viewing, Trained Services Dogs | | |
| Trail Uses NOT Allowed | Biking, Dog Walking, Plant Harvesting, Camping, Fishing, Drone Use | | |
| Typical Grade | 2.6% | Max = 12.9% | |
| | Standard Ramp Grade is 8.3% | | |
| Typical Cross Slope | 2.1% | Max = 8.6% | |
| Typical Tread Width | 22 in (55.5 cm) | Min = 14 in (35.6 cm) | |
| Surface Type | Sand | | |
| Surface Category | 0.0 % of Trail is Paved | 28.8 % of trail is Soft | |
| | 2.3 % of Trail is Hard | 54.6 % of trail is Very Soft | |
| | 14.3 % of Trail is Firm | | |
| Obstructions: | | | |
| Type: | Size (Height): | Remaining Tread: | Location: |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a (n/a m) |
| n/a | n/a in (n/a cm) | n/a in (n/a cm) | n/a ft (n/a m) |
| Warning: Trail conditions may have changed since 2024-09-09 when this trail was assessed. Temporary obstacles were not mapped. | | | |
| Maximum grades and cross-slopes may vary. Obstructions less than <u>5 in (12.7 cm)</u> or outside of the tread area <u>36 in (91.4 cm)</u> wide by <u>72 in (182.9 cm)</u> high were not reported. Minimum clearance width boundaries were at least <u>???</u> in (<u>???</u> cm) high | | | |
| Data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP). | | | |

Trail Access Information Summary – East Trail

| | | | |
|---|---|----------------------------------|-------------------|
| Park Name | South Cape May Meadows | | |
| Trail Name | East Trail | | |
| Length | 0.5 mi (0.8 km) One Way 1.0 mil (1.6 km) Round Trip | | |
| Elevation Gain | 21.2 ft (6.45 m) | | |
| Elevation Loss | 26.1 ft (7.95 m) | | |
| Trail Uses Allowed | Walking, Jogging, Photography, Wildlife Viewing, Trained Services Dog | | |
| Trail Uses NOT Allowed | Biking, Dog Walking, Plant Harvesting, Camping, Fishing, Drone Use | | |
| Typical Grade | 1.9% | Max = 12.3% (near dune crossing) | |
| | Standard Ramp Grade is 8.3% | | |
| Typical Cross Slope | 1.3% | Max = 5.4% | |
| Typical Tread Width | 83 in (210.9 cm) | Min = 36 in (91.4 cm) | |
| Surface Type | Crushed Stone (Fines) | | |
| Surface Category | 0.0 % of Trail is Paved | 0.0 % of trail is Soft | |
| | 1.8 % of Trail is Hard | 2.0 % of trail is Very Soft | |
| | 96.2 % of Trail is Firm | | |
| Obstructions: | | | |
| Type: | Size (Height): | Remaining Tread: | Location: |
| Water Bar | 8 in (20.3 cm) | 0 in (0.0 cm) | 49.8 ft (15.18 m) |
| Warning: Trail conditions may have changed since 2024-09-09 when this trail was assessed. Temporary obstacles were not mapped. | | | |
| Maximum grades and cross-slopes may vary. Obstructions less than <u>5 in (12.7 cm)</u> or outside of the tread area <u>36 in (91.4 cm)</u> wide by <u>72 in (182.9 cm)</u> high were not reported. Minimum clearance width boundaries were at least <u>???</u> in (<u>???</u> cm) high | | | |
| Data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP). | | | |